



B & V PRODUCTS 2019-23 Chevy Silverado/ GMC SIERRA 1500

CONSOLE SAFE

PART # 7022-1000-19

*NOT COMPATIBLE WITH HD MODELS

www.bvnproducts.com




MADE IN THE USA

TOOLS REQUIRED: 10mm socket and ratchet.

9/29/23

Notes to the Technician/Installer:


Do not attempt the installation of any B&V product without first reading the detailed instructions. B&V will not warrant damaged parts or the vehicle due to altered installation procedures.




1. Cover the seats with a protective cover prior to beginning the console safe installation. Open the center console lid, empty the console and remove the factory liner (if equipped). Remove the two factory 10mm hex bolts from the bottom of the console. Remove the factory hardware retaining the side rails from the console and remove the side rails (not shown).




2. Carefully position the console safe into the factory console well, making sure you do not scrape the sides of the factory console.



3. Make sure the console safe is seated in the console well with the sides flush and square in the corners. Reinstall the factory bolts to secure the console to the vehicle.



4. Install the supplied carpet inserts into the bottom of the console well and the console safe (prototype inserts shown, production inserts may differ).



5. Align the supplied console safe tray and carpet insert into the upper opening in the console safe (prototype insert shown, production insert may differ).



6. Finished installation. **For the vehicle owner:** Follow the supplied detailed instructions and choose your lock combination. There is a spare copy of the lock combination instructions below.

Part #7022-100C -19


Quantity:	Description:	Part Number:
1	Console Safe Complete	7022-1100-19
1	Console Tray	7022-1070-19
1	Installation Hardware Kit	7022-1902-19
1	Console Safe Carpet Insert	7022-0121-19
1	Console Safe Well Carpet Insert	7022-0122-19
1	Console Safe Tray Carpet Insert	7022-0123-19

Warranty. B & V products (Manufactured by Fralo Industries) are warranted against defects in workmanship for a period of one (1) year from the date of purchase. Fralo's liability under this warranty is limited to the repair or replacement, at the option of Fralo, of the products or parts thereof covered by this Warranty, provided that Buyer provides all necessary materials. Fralo's obligation under this warranty shall not arise unless written notice of a warranty claim is made to Fralo. Fralo may require that the product in question be delivered for inspection, freight prepaid, at Fralo's office in Erie, Pennsylvania, or some other location designated by Fralo. THE REPAIR OR REPLACEMENT WARRANTY HEREIN SET FORTH IS THE EXCLUSIVE WARRANTY GIVEN BY FRALO FOR ITS GOODS. THIS WARRANTY IS GIVEN IN LIEU OF ANY OTHER WARRANTIES, WHETHER WRITTEN OR ORAL, EXPRESS OR IMPLIED. ANY AND ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE ARE HEREBY EXPRESSLY EXCLUDED BY FRALO. FRALO NEITHER ASSUMES, NOR DOES IT AUTHORIZE ANY OTHER PERSON TO ASSUME ON ITS BEHALF, ANY OTHER LIABILITY IN CONNECTION WITH THE SALE OF ITS GOODS

Setting your own combination:

NOTE: The opening combination code is preset to 0-0-0

1. Combination must be set to the current opening combination code prior to resetting.
2. Set knob to the locked position.
3. The code reset button is located on the side of the lock. Press and hold the reset button.
4. Set your personal combination by turning the number dials to the desired combination.
5. Release the reset button and the new opening combination code is set.
6. To lock, rotate one or more number dials after the locking knob is turned to the locked position.
7. To open the lock, turn the number dials to your personal combination.



Discovering an unknown combination using the key:

1. Insert the key and turn it counter clockwise to unlock the safe. **IMPORTANT:** The knob will remain in the locked position.
2. With the key in the unlocked position, turn each number dial until they stop.
3. Once all the number dials have stopped, the current opening combination code has been discovered and can now be reset.